Appendix C2

Environment Agency maintained assets. Provided by the Environment Agency in January 2009.

NFCDD ID	AssetReference	AssetType	Maintainer	Inspection Date	Inspected By Name	ResidualLife	Urgency	Recommendations	Overall Condition	Worst Condition	AssetInspectionComments	OverallCondition DataQuality
824	0520222010501L01014	flood defence structure	local authority	6/2/06	SB	11 - 20	routine	Clear vegetation from flood arches	2	2	Some flood arches blocked . Structurally good.	5
842	0520222010801L05001	flood defence structure	local authority	7/31/08	icooper	11 - 20	no repairs	R28 silt bars	3	3	1,6- D5 with D6. D3, D4, D5- minor D48	1
871	0520222010501L01019	flood defence structure	Environment Agency	6/2/06	SB	>20	no repairs	Continue Routine Inspection	2	2	Some minor cracks in wingwallsSome handrails on footbridge slightly loose, no riskTree on U/S LB requires trimming	5
913	0520222011015L01003	flood defence structure	Environment Agency	2/29/08	IC/KP	11 - 20	routine	continue inspections	2	2	externally good, assume it functions OK	1
983	0520222010501L01042	flood defence structure	Environment Agency	6/6/06	AF	>20	no repairs	Continue Routine Inspection	2	2	All left bank wall revetments are in very good condition, no cracks or material loss. Sluice gate has collected minor debris, gate in good condition	5
984	0520222010501L01043	flood defence structure	Environment Agency	6/6/06	SB	>20	no repairs	Continue Routine Inspection	2	3	OK. Some debris collected in gate	5
985	0520222010501L01044	flood defence structure	Environment Agency	6/6/06	SB	>20	no repairs	Continue Routine Inspection	2	3	All looks OK, some small pieces of debris collected on gateFence rotting slightly	5
988	0520222010501L01040	flood defence structure	local authority	6/6/06	SB	>20	no repairs	Continue Routine Inspection	1	1	Some vegetation growing in mattressingBridge Good	5
1087	0520222010901L01021	flood defence structure	Environment Agency	5/2/06	SB	>20	routine		2	2		1
1281	0520222010701L01057	flood defence structure	local authority	10/2/08	icooper	>20	no repairs	R36	2	2	in good condition, all arches clear, however land either side higher than arch bed in places.	1
1283	0520222010601L14009	flood defence structure	local authority	4/23/08	MD/IC	>20	no repairs	ASM Enforcement inform owner to clear culverts	1	2	Debris accumulating in culverts esp. larger of the two (r/h).	1
1286	0520222010601L14002	flood defence structure	Environment Agency	4/23/08	MRD/IC	>20	no repairs	Continue inspections	1	1	Flaps locked closed at time of inspection, locking mechanism checked visually and ok.	1
1289	0520222010601L15001	flood defence structure	internal drainage board	4/23/08	MRD/IC	>20	routine	ASM - enforce crack & joint repairs & veg. removal. Check operation of flap.	3	3	1-2-4-5-9-11-13-14-eni-1 due to high water levels, 3,5 - trees growing, slabs cracked, sealant missing.	1
1296	0520222010601L15002	flood defence structure	internal drainage board	4/18/08	MRD	>20	no repairs	Continue routine inspections (if FD asset).	2	2	Entrance clear minor vegetation in channel. Is this FD structure?	1
1321	0520222010602L01001	flood defence structure	local authority	4/9/08	md/ic	>20	no repairs	continue inspections	2	2	channel contains weeds and poss silt where channel widens at confluence.	1
1434	0520222010605R01004	flood defence structure	local authority	4/15/08	IC	11 - 20	routine	remove vegetation from masonry walls	3	3	2- eroding at d/s end. 6,8- moss and woody growth d/s of sluice. Gate replaced. CB- masonry, wood debris and silt.	1
1439	0520222010605R01005	flood defence structure	local authority	4/15/08	IC	11 - 20	routine	Repair pier	3	4	3,5,8-ENI-1. Pier end eroded, rebar exposed	5
1519	0520222010602R01002	flood defence structure	Environment Agency	4/9/08	mrd/IC	>20	routine	Continue inspections and routine maintenance.	2	3	4-10-ENI-1.Cracks on approach ramp (Footbridge Right Bank). CS4 and CS5, FI3 and FI4, US Piling corroding.	1
1524	0520222010601R02001	flood defence structure	internal drainage board	4/9/08	mrd/ic	11 - 20	routine	ASM Enf inform owner,replace soil, repair baskets.	4	4	1-2-ENI-2. vegetation growth in front of crest and wingwalls,unable to see to inspect Soil on gabion baskets is eroding. Some deformation of baskets and stone loss.	1
1529	0520222010601R01003	flood defence structure	Environment Agency	4/9/08	mrd/ic	>20	routine	continue inspection	2	3	1- uneven, poss scoured/movement in apron under footbridge. Minor cracking to conc. render. Minor spalling to coping brickwork.	1
1534	0520222010601R02002	flood defence structure	Environment Agency	4/9/08	mrd/ic	>20	routine	monitor scour, paint piles, conc. rep. FI3, rep. l, brickwork repair. C/S FI7	2	3	piling coroding & scour behind, crack to FI3 @ joint piling, minor cracking in gunnite,significant masonry loss & veg. to FI7 &CS7. Spalling to d/s bridge abut. gate open at time of insp.	1
1592	0520222010603L03001	flood defence structure	Environment Agency	4/9/08	MRD/tb	>20	no repairs	Cont. to inspect.	2	3	CS1, CS2 =minor corroding. FI1, FI2= minor loss of coating. CB= immed d/s of sluice not seen. Boom appears to be below water surface. Some ground subsidence around control hut.	1